

Alva's Institute of Engineering & Technology Shobhavana Campus, Mijar, Moodbidri, D.K - 574225

Phone: 08258-262725, Fax: 08258-262726

Department of Electronics & Communication Engineering

(Accredited by NBA)

Ref. No. AIET/LAB-SRV/2022-23/01

Date:03-08-2022

To, HOD, Dept. of ECE, AIET, Mijar

PERMISSION TO DO SERVICING OF THE FOLLOWING ITEMS

Sir,

With respect to above subject, it is found that, few equipment's from the ADC LAB, DSD LAB and HDL LAB require servicing. The details of equipment and required servicing are as follows. Hence I request you to give the permission to carry out the servicing.

SI. No.	Name of Equipment	Quantity	Equipment No.	Laboratory	Type of Fault	Can be done AIET (Yes/No)
1	FIXED POWER SUPPLY	2	AIET/ECE/EDI LAB/2010/FIXED POWER SUPPLY/07. AIET/ECE/EDI LAB/2010/FIXED POWER SUPPLY/11	ADC LAB	No regulated output	YES
2	HDL KIT	2	AIET/ECE/HDL KIT/03 AIET/ECE/HDL KIT/04	HDL LAB	Loose contact in cable Unable to dump program	YES
3	TRAINER 3 KIT		AIET/ECE/TRAINER KIT/03 AIET/ECE/TRAINER KIT/06 AIET/ECE/TRAINER KIT/09	DSD LAB	Socket problem, IC getting heated	YES

Mr. Joe Fernandes

Foreman

Dept. of ECE, AIET, Mijar

HOD

H. O. D.

Dept. Of Electronics & Commer ktva' Institute of Engg. & Techn Mijar, MOODBIDRI - 574 224



Alva's Institute of Engineering & Technology Shobhavana Campus, Mijar, Moodbidri, D.K - 574225

Phone: 08258-262725, Fax: 08258-262726

Department of Electronics & Communication Engineering

(Accredited by NBA)

Ref. No. AIET/LAB-SRV/2022-23/02

Date: 12-08-2022

To, HOD, Dept. of ECE, AIET, Mijar

Sir,

UPDATES ON SERVICING

With respect to letter no. Ref. No. . AIET/LAB-SRV/2022-23/01 dated on 03-08-2022, the following equipment are serviced at the AIET. The details are provided in the annexure -I.

Annexure - I

SI.	Name of	Almexure – I						
No.	Name of Equipment	Quantity	Equipment No.	Type of Fault	Serviced Date	Name and Signature of the person who serviced the instrument.		
	SUPPLY	2	AIET/ECE/EDI LAB/2010/FIXED POWER SUPPLY/07 AIET/ECE/EDI LAB/2010/FIXED POWER SUPPLY/11	No regulated output	10-08-2022	Joe Fernandes		
2	HDL KIT	2	AIET/ECE/HDL KIT/03 AIET/ECE/HDL KIT/04	Loose contact in cable Unable to dump program	10-08-2022	P Mahesh Rao		
3	TRAINER KIT	3	AIET/ECE/TRAINER KIT/03 AIET/ECE/TRAINER KIT/06 AIET/ECE/TRAINER KIT/09	Socket problem, IC getting heated	09-08-2022	Sudha		

#

Mr. Joe Fernandes

Foreman

Dept. of ECE, AIET, Mijar

DV.9

HOD

H. O. D.

Open. Of Electronics & Communication www.institute of Engg. & Technolog, Mijar, MOODBIDRI - 574 225