

R. New

iew

String Current Details

Project- ALVAS EDUCATION FOUNDATION

Site- ENGINEERING COLLEGE, KUMARADHARA BLOCK

Date- 31/1/2022

Engineering College			Kumaradhara	Nursing	
String No.	Inv-1	Inv-2	Inv-1	Inv-1	Inv-2
1	6.8 A	6.7 A	5.8 A		
2	6.1 A	6.6 A	6.1 A		
3	6.5 A	6.3 A	6.2 A		
4	6.4 A	6.7 A	5.9 A		
5	6.3 A	6.8 A	6.8 A		
6	6.1 A	6.5 A	6.1 A		
7	6.4 A	6.4 A	6.5 A		
8	6.5 A	6.8 A	6.3 A		
9	6.4 A	6.7 A	6.1 A		
10	6.3 A	6.1 A	6.3 A		
11					
12					

Remarks:

Attended By

Name - VIJETH

Signature - 

Checked By

Name -

Signature - 
Electrical Incharge
Alva's Education Foundation (R.)
Moodubidre - 574 227, D.K.


PRINCIPAL
Alva's Institute of Engg. & Technology,
Moodubidre - 574 225, D.K.

RENEW

Inverter PM Report

Project: ALVA'S EDUCATION FOUNDATION
 Site: ALL BLOCK Date: 31/1/2022

S.No.	Task	Frequency	Check	Supporting Images	Remarks
1	Cleaning (heat sink fins/filters)	M	☒		Cleaned
2	Cleaning of Control & Power electronic equipments	M	☒		Cleaned
3	Checking of Surge Arresters	M	☒		Checked
4	Check protective fuse	A	☐		
5	Checking of control devices (DC/AC Isolator/Breaker)	A	☐		
6	Ventilator Operation	A	☐		
7	Check LCD Display of Inverters and note down all input and output parameters	M	☒		Checked
8	Mechanical Fixing of Inverters	3M	☐		
9	Earthing of Inverters	3M	☐		
10	String/Cable Connection	F	☐		
11	String Ampere Checking	M	☒		Checked
12	Abnormal Heating/Rise in Temperature	F	☐		
13	Check for any odd/foul smell	F	☐		

For ReNew Power Ventures Pvt Ltd

Name: VIJETH
 Signature: [Signature]
 Date: 31/1/2022

Name:
 Signature:
 Date:

[Signature]
 Customer's Charge
 Alva's Education Foundation (R.)
 Moodubidire - 574 227, D.K.

[Signature]
 PRINCIPAL
 Alva's Institute of Engg. & Technology
 Moodubidire - 574 225, D.K.

Solar Module/Array PM Report

Project: ALVA'S EDUCATION FOUNDATION Date: 31/1/2022
 Site: All Block

S.No.	Task	Frequency	Check	Supporting Images	Remarks
1	Physical Inspection of Panels for damages/cracks	M	☒		ok
2	Check module junction box for burning spot/damage	6M	☒		Checked
3	Check for yellowish marks	3M	☐		
4	Physical Inspection of DC Connectors	3M	☐		
5	Check for Module Alignment	3M	☐		
6	Earthing of Modules	3M	☐		
7	Module Cable Dressing	6M	☒		ok

For ReNew Power Ventures Pvt Ltd

Name: VISHAKH
 Signature: [Signature]
 Date: 31/1/2022

Name:
 Signature:
 Date:

Customer Sign: [Signature]
 Electrical Incharge
 Alva's Education Foundation
 Moodubidire - 574 227, D.K.

[Signature]
 PRINCIPAL
 Alva's Institute of Engg. & Technology
 Moodubidire - 574 225, D.K.

Earthing Strip I.A. PIA Report

Project: ALVA'S EDUCATION FOUNDATION Date: 31/1/2022
 Site: All Block

S.No.	Task	Frequenc.	Check	Supporting Images	Remarks
1	Check earthing strip connections	M	☒		checked
2	Check continuity of LA grounding	M	☒		ok
3	Earth pit condition	3M	☐		
4	Note down reading of surge counter	3M	☐		

For FeNew Power Ventures Pvt Ltd

For FeNew Power Ventures Pvt Ltd

Name: VISHESH
 Signature: [Signature]
 Date: 31/1/2022

Name: [Signature]
 Signature: Electrical Incharge
 Date: Alva's Education Foundation
Moodubidire - 574 227, D.K.

[Signature]

PRINCIPAL

Alva's Institute of Engg. & Technology,
 Moodubidire - 574 225, D.K

RMS PM Report

Project: ALVA'S EDUCATION FOUNDATION Date: 31/1/2022
 Site: Au Gad

S.No.	Task	Frequency	Check	Supporting Images	Remarks
1	General Cleaning of datalogger and its enclosure	1M	☒		Cleaned
2	Check LED Display of datalogger and take a picture	F	☒		Oh
3	Mechanical Fixing of datalogger	3M	☐		
4	Earthing of datalogger enclosure	3M	☐		
5	Wiring connection	F	☒		Oh
6	Portal Monitoring	D	☒		Oh
7	Check UPS output	1M	☒		Checked

For ReNew Power Ventures Pvt Ltd

Name: VIJAYAN
 Signature: [Signature]
 Date: 31/1/2022

Customer Signature

Name: [Signature]
 Signature: Electrical Incharge
 Date: Alva's Education Foundation (R.)
Moodubidire - 574 227, D.K.

[Signature]

PRINCIPAL

Alva's Institute of Engg. & Technology,
 Moodubidire - 574 227, D.K.

PV Module Cleaning Report



Site Name	ENGINEERING COLLEGE
Total no. of modules installed	200
Cleaning Start Date	29/03/2022
Cleaning End Date	29/03/2022

Date of cleaning	No. of Modules cleaned
29/03/2022	200




PRINCIPAL
Institute of Engg. & Technology,
Moodbidri - 574 225, D.K.

PV Module Cleaning Report



Before Cleaning Pictures



After Cleaning Pictures





PV Module Cleaning Report

INVERTER

Before Cleaning Pictures


After Cleaning Pictures



PV Module Cleaning Report



WEBDYN



A handwritten signature in green ink, likely of the Principal.

PRINCIPAL

Alva's Institute of Engg. & Technology,
Taljar. MOGGBIDRI - 574 225, D.K